

Former Boiler Room as a Brewery – Northern Stacks, Fridley, MN

Christopher Thompson, PE October 24, 2017













X 1/1 1/1


是我们们

. .













Regulatory Status

- CERCLA Site
- MPCA Voluntary Investigation & Cleanup Site
- MPCA RCRA Site
- MPCA Petroleum Brownfields Site
- US Navy GW Operable Unit
- BNSF Main Line within 50 feet



Environmental Response Actions

- Asbestos Abatement & Demolition
- Lead Containing Paint
- Petroleum Impacts to Soil & GW
 - Soil Excavation & Re-use
 - Off-Site Soil Disposal
- Chlorinated Solvent Soil Contamination
 - Soil Chemical Oxidation
 - Site Specific SLVs and Soil Excavation in Green Space
 - Vapor Mitigation



















Building Modifications


- Water-Proofing exterior walls
- New Roof Membrane
- Interior Demolition
- Structural Modifications
- Electrical, Sewer, Water into Building
- Filling and New Floor to Address Rising Water Table
- Wall Assessment & Repair

















The Science You Build On.



